



AC 100



Amplifier for pyranometers.

User manual

version 1.3
August 2015



LEIDERDORP INSTRUMENTS
Dijkgravenlaan 17
NL-2352 RN Leiderdorp
The Netherlands
Phone: --71-541 55 14
Fax: --71-541 89 80
email: info@leiderdorpinstruments.nl
web: <http://www.leiderdorpinstruments.nl>

Important user information

Reading this entire manual is recommended for full understanding of the use of this product.



The exclamation mark within an equilateral triangle is intended to alert the user to the presence of important operating and maintenance instructions in the literature accompanying the instrument.

Should you have any comments on this manual we will be pleased to receive them at:
info@leiderdorpInstruments.nl

Leiderdorp Instruments reserve the right to make changes in the specifications without prior notice.


WARRANTY AND LIABILITY

Leiderdorp Instruments guarantees that the product delivered has been thoroughly tested to ensure that it meets its published specifications. The warranty included in the conditions of delivery is valid only if the product has been installed and used according to the instructions supplied by Leiderdorp Instruments.

Leiderdorp Instruments shall in no event be liable for incidental or consequential damages, including without limitation, lost profits, loss of income, loss of business opportunities, loss of use and other related exposures, however caused, arising from the faulty and incorrect use of the product.

Copyright © 1993 Leiderdorp Instruments

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system or transmitted in any form or by any means, without permission in written form from the company.



LEIDERDORP INSTRUMENTS
Dijkgravenlaan 17
NL-2352 RN Leiderdorp
The Netherlands
Phone: --71-541 55 14
Fax: --71-541 89 80
email: info@leiderdorpinstruments.nl
web: <http://www.leiderdorpinstruments.nl>

Table of contents.

1. GENERAL INFORMATION	4
1.1 INTRODUCTION	4
1.2 ADDITIONAL EQUIPMENT REQUIREMENTS.....	4
2. TECHNICAL SPECIFICATIONS	4
3. INSTALLATION	5
3.1 LOCATION.....	5
3.2 CABLING	5
4. GAIN SETTING	6
APPENDIX A ORDERING INFORMATION	8
A.1 DELIVERY	8
A.2 ORDERING SPECIFICATIONS.....	8
A.3 OPTIONS	8
A.4 SPARE PARTS	8
A.5 ACCESSORIES	8
A.6 RELATED PRODUCTS.....	8



LEIDERDORP INSTRUMENTS
Dijkgravenlaan 17
NL-2352 RN Leiderdorp
The Netherlands
Phone: --71-541 55 14
Fax: --71-541 89 80
email: info@leiderdorpinstruments.nl
web: <http://www.leiderdorpinstruments.nl>

1. GENERAL INFORMATION

1.1 INTRODUCTION

The AC100 amplifies the output voltage of radiation sensors to a level suited for data acquisition equipment and transmission over long cables. The AC100 amplifier has technical specifications that match the radiation sensors' accuracy and signal levels. The amplifier can be adapted to the sensitivity of the sensor so that a calibrated output current is obtained. The amplification factor is factory set. If not specified when ordered, it is set to 200 so that a reasonable signal level results for an average sensor. The user can change the amplification factor if required. This manual describes the details of how to do this.


1.2 ADDITIONAL EQUIPMENT REQUIREMENTS

The AC100 must be powered with a DC voltage of 8..28 VDC. A complete measuring set-up consists of a sensor, the AC100 amplifier, a power source and a read-out device (e.g. a DC voltmeter).

2. TECHNICAL SPECIFICATIONS


- input voltage range:
 - minimal full scale input: 3 mV
 - maximum full scale input: 1000 mV
- amplification factor range: 1...500
- converter output range: approx. -1.5...+3.5 V
- factory gain setting: not set, specify required amplification with order
- calibration resistor: calculate the required amplification as follows:

$$A = (100\text{kOhm}/\text{user resistor in kOhms}) - 1$$
- input impedance: 1 MOhms
- ambient temperature: operating: -20...50 °C
storage: -30...70 °C
- zero drift: <0.05 mV/°C
- range drift: <0.01%/°C
- initial accuracy: range factory setting 0.1%
zero factory setting 0 +/- 0.2 mV
- supply current (no load): <30 mA
- output impedance: <10 Ohms
- maximum supply voltage: 28 Volt
- minimum supply voltage: 8 Volt
- response time: <1 s



LEIDERDORP INSTRUMENTS
 Dijkgravenlaan 17
 NL-2352 RN Leiderdorp
 The Netherlands
 Phone: --71-541 55 14
 Fax: --71-541 89 80
 email: info@leiderdorpinstruments.nl
 web: <http://www.leiderdorpinstruments.nl>

The dimensions of the amplifier are shown in the figure below.



The cable glands are suited for cables with a diameter of 3.5 – 6 mm.

3. INSTALLATION

3.1 LOCATION



The housing of the AC100 is IP65 protected. This means that the amplifier may be placed outside without special protection. However, some precautions are recommended:

- do not mount the AC100 on a dark background in direct sunshine (wall/roof)
- if possible shelter the amplifier from rain and snow
- avoid mechanical stress

3.2 CABLING

Make sure that the diameter of the connection cables matches the cable glands (3.5..6 mm). Avoid mechanical stresses on the cables.


Keep the cables as short as possible and keep them away from obvious sources of electrical fields such as power lines, mains outlets etc. The following figure shows how the amplifier is connected:




LEIDERDORP INSTRUMENTS
 Dijkgravenlaan 17
 NL-2352 RN Leiderdorp
 The Netherlands
 Phone: --71-541 55 14
 Fax: --71-541 89 80
 email: info@leiderdorpinstrument.nl
 web: <http://www.leiderdorpinstrument.nl>

4. GAIN SETTING

The gain factor of the amplifier can be changed to get a calibrated output of the converter. Three 'user resistors' in the converter can be used to determine the gain factor. The resistors can be accessed by opening the converter and removing the connection board as shown below.



The position of the user resistors is shown in the figure below.




User resistors.
Three resistors can be placed in series to obtain the desired value.

The amplification is calculated as follows:

$$A = \frac{100 \text{ kOhm}}{\text{user resistor (in kOhms)}} - 1$$

So, if a resistor of 1kOhm is installed, the output will be 99 times the input voltage.

The resistor that determines the amplification may consist of three resistors in series. This allows the user to install a resistor value that matches the sensor calibration factor. The resistors must have a temperature coefficient of +/- 50 ppm/K (regular low-cost metal film resistors). The accuracy of the resistor value is directly reflected in the output accuracy of the converter.



LEIDERDORP INSTRUMENTS
Dijkgravenlaan 17
NL-2352 RN Leiderdorp
The Netherlands
Phone: --71-541 55 14
Fax: --71-541 89 80
email: info@leiderdorpinstruments.nl
web: <http://www.leiderdorpinstruments.nl>

For example:

If a sensor with a full scale output of 5.22 mV is used and an output voltage of 1 V full scale is required, the user resistor is calculated as follows:

Required amplification = $1000 \text{ mV} / 5.22 \text{ mV} = 191.6$

$A = 100 / \text{user resistor} - 1$, or $\text{user resistor} = 100 / (A + 1)$

$\text{user resistor} = 100 / (191.6 + 1)$ so

$\text{user resistor} = 0.519 \text{ k}\Omega = 519 \text{ }\Omega$

A resistor of 519 Ohms is obtained from:


332 + 182 + 4.7 or

475 + 22.1 + 22.1 or

100 + 392 + 26.7 etc.


The amplifier has an input resistance of 1 M Ω . It may be necessary to compensate for this resistance in the amplification factor if the output impedance of the sensor is too high (generally not required for pyranometers).

If the amplification is changed it may be necessary to re-adjust the zero setting. To do this, short-circuit the input terminals '+' and '-' with a short wire (do not connect them to ground) and adjust the output with the potentiometer (see figure below).



Potentiometer for zero adjustment.

The output should be 0 mV +/- 0.2 mV. Wait for at least 30 minutes after soldering the user resistors before adjusting the zero level (the heated resistor leads, and the terminals they are soldered to, form a thermo-couple that generates an offset voltage in the amplifier circuit).



LEIDERDORP INSTRUMENTS
 Dijkgravenlaan 17
 NL-2352 RN Leiderdorp
 The Netherlands
 Phone: --71-541 55 14
 Fax: --71-541 89 80
 email: info@leiderdorpinstruments.nl
 web: <http://www.leiderdorpinstruments.nl>

APPENDIX A Ordering information

A.1 DELIVERY

- AC100 amplifier
- Mounting brackets
- Calibration certificate
- Manual

A.2 ORDERING SPECIFICATIONS

- AC100, with amplification adjusted to a specified sensor (to give 1 V/1000W/m²): specify desired gain or sensor outputvoltage at full scale.

A.3 OPTIONS

The amplifier can be ordered without the standard housing.

A.4 SPARE PARTS


There are no spare parts for this product.

A.5 ACCESSORIES

There are no accessories for the AC100.

A.6 RELATED PRODUCTS

AC-420	4...20 mA amplifier for pyranometers
LI-19	hand-held read-out unit and data logger for radiation sensors



LEIDERDORP INSTRUMENTS
Dijkgravenlaan 17
NL-2352 RN Leiderdorp
The Netherlands
Phone: --71-541 55 14
Fax: --71-541 89 80
email: info@leiderdorpinstruments.nl
web: <http://www.leiderdorpinstruments.nl>